


Reparatursatz zur Membranpumpe für 321 & 301



Artikelnummer T206-321-100
beinhaltet pos. 1-14

| Pos: | Anzahl | Zeichnungsnummer | Artikel |
|------|--------|------------------|---|
| 1 | 2 | T07-100-009 | Äussere Membrane, Viton |
| 2 | 2 | T07-100-010 | Innere Membrane, Teflon |
| 3 | 1 | L70-604-2000 | Saugschlauch, "Multi-Oil" ½" x 2.000 mm |
| 4 | 2 | L70-604-425 | Saugschlauch, "Multi-Oil" ½" x 425 mm |
| 5 | 1 | L70-604-180 | Saugschlauch, "Multi-Oil" ½" x 120 mm |
| 6 | 1 | L63-42-20-12 | Kugellager, 6004 RS 42x20x12 |
| 7 | 2 | L63-15-35-11 | Kugellager, 6202 2RSH |
| 8 | 1 | L92-115-000 | Äusserer Seegering 15 mm |
| 9 | 8 | L93-615-018 | O-Dichtung 15,6 x 1,78 mm |
| 10 | 10 | L99-118-12-02 | Dichtung, Viton Ø13x19x2 mm |
| 11 | 4 | L99-513-000 | Stahlkugel Ø13, Edelstahl |
| 12 | 4 | T07-100-014 | Ventilsitz für Pumpe 07 |
| 13 | 2 | L82-508-016 | Schraube, 8 x16 mm |
| 14 | 1 | L85-15-21-01 | Dichtung, 15x21x1 mm |

Presented by / Überreicht durch:

